## Product Identification - Microsoft DCOM Hardening Patch

The **Active** and **Active Mature** products listed below are **directly** affected by the Microsoft DCOM Hardening patch:

## **Directly Affected Products**

- FactoryTalk® Services
- RSLinx® Classic
- FactoryTalk® Linx
- FactoryTalk® Linx Gateway
- FactoryTalk® Linx
  Data Bridge
- FactoryTalk® View Site Edition
- FactoryTalk® ViewPoint
- FactoryTalk® Batch
- FactoryTalk<sup>®</sup> Edge Gateway<sup>™</sup>
- ThinManager®
- FactoryTalk® EnergyMetrix™

- FactoryTalk® ProductionCentre®
- FactoryTalk® Transaction Manager
- FactoryTalk® VantagePoint®
- Pavilion8®
- Emonitor® Condition Monitoring Software
- KEPServer Enterprise

The **Active** and **Active Mature** products listed below are **indirectly** affected by the Microsoft DCOM Hardening patch:

## **Indirectly Affected Products**

- FactoryTalk® Policy Manager
- FactoryTalk® System Services
- FactoryTalk® Linx CommDTM
- ControlFLASH™
- ControlFLASH Plus™
- Studio 5000 Logix Designer®
- Studio 5000 View Designer®
- Studio 5000® Logix Emulate™
- Studio 5000 Architect®
- FactoryTalk® Logix Echo
- FactoryTalk® AssetCentre
- FactoryTalk® Historian SE
- Application Code Manager
- FactoryTalk® View Machine Edition

- RSNetWorx™
- RSLogix 5000®
- RSLogix 500®
- RSLogix<sup>™</sup> 5
- FactoryTalk® Metrics
- FactoryTalk® Production Management
- FactoryTalk® Quality Management
- FactoryTalk® Warehouse Management
- FactoryTalk® EI Hub
- FactoryTalk® PharmaSuite®
- FactoryTalk® AutoSuite
- FactoryTalk® CPGSuite®

- FactoryTalk® Analytics™
   EdgeML
- FactoryTalk® Analytics™
   DataView
- FactoryTalk® Analytics™ DataFlowML
- FactoryTalk® Analytics™ AugmentedModeler
- FactoryTalk® Historian -ThingWorx Connector
- AADvance® OPC Portal
- AADvance® OPC Standalone
- Trusted® OPC Portal

The **Active** and **Active Mature** products listed below are <u>unaffected</u> by the Microsoft DCOM Hardening patch:

Unaffected Products		
<ul> <li>FactoryTalk® Activation         Manager</li> <li>FactoryTalk® Updater</li> <li>Studio 5000® Add On         Profiles</li> </ul>	<ul> <li>PanelView™Plus 6 / 7</li> <li>PlantPAx® MPC</li> <li>PlantPAx® Process Object Online Configuration Tool</li> </ul>	<ul> <li>Connected Components         Workbench™</li> <li>FactoryTalk® Historian ME</li> </ul>

The following products' lifecycle state is **End of Life** or **Discontinued**. No action is planned to address the Microsoft DCOM Hardening patch, regardless of the effect on the product, based on the lifecycle state:

End of Life or Discontinued Products			
FactoryTalk® Performance     Management	RSView®32 (Active Display)	• GuardPLC™ OPC Server	

Rockwell Automation products may be **directly** or **indirectly** affected by Microsoft's patch. For example,

- ThinManager® is **directly** affected because it uses DCOM between the ThinManager® UI and a remote ThinServer™ service
- FactoryTalk® Edge Gateway™ is **directly** affected because it offers an OPC-DA ingress point that uses DCOM to establish connection
- Studio 5000 Logix Designer® is **indirectly** affected because it uses FactoryTalk® Services, specifically FactoryTalk® Security, and FactoryTalk® Services uses DCOM between the FactoryTalk® Directory server and FactoryTalk® Directory client
- FactoryTalk® Product Management is indirectly affected because it uses
   FactoryTalk® ProductionCentre®, and FactoryTalk® ProductionCentre® uses
   FactoryTalk® Services and FactoryTalk® Live Data